



Tijuana, Baja California, México July 3rd 2024

HYDROGATION SERVICE REFERENCE LETTER

To whom it may concern:

Hereby we inform you that considering the problems we had in the hotel mainly due to the waste of water, caused by the backwashing processes of the filters of the water softening system in addition to the expense of industrial salt, electrical energy and poor quality of water from the softeners, it was decided in 2017 to install the Hydrogation system, which since that date has worked properly and allowed savings by eliminating water waste and the expenses generated by the operation of the softeners.

To date, due to the use of Hydrogation, our pipes and hydraulic system are generally free of scale, calcium or minerals that affect the operation of showers, faucets or the whiteness of the linens processed in our laundry.

Given the above, I highly recommend the use of this system, in addition to this, the service provided by Brandt Smith and his team has been excellent.

Sincerely

A handwritten signature in blue ink, appearing to read 'Baltazar Pille', written over a horizontal line.

BALTAZAR PILLE
Gerente General / General Manager

HYATT PLACE TIJUANA
Blvd. Agua Caliente 10488 Col. Aviación, Tijuana BC, 22014 Mexico.
T 664 900 1234 M 664 450 0691 E baltazar.pille@hyatt.com
hyattplacetijuana.com

HYATT PLACE TIJUANA

Blvd. Agua Caliente 10488
Col. Aviación
Tijuana, Baja California 22014, MEX

T 664 900 1234

E hyattplace.tijuana@hyatt.com